

First we need to make sure we have a complete compliment of component parts. Please use the following check list to ascertain this.

Designator	Description	QTY	Code	Check
R4, R5, & R15	4.7Ω 2W Carbon Film Resistor	3	Yellow-Violet-Gold	<input type="checkbox"/>
R10, R11 R12, & R13	100Ω 2W Metal Film Resistor	4	Brown- Black- Brown	<input type="checkbox"/>
R6, R7, R8, & R9	10Ω 1/2W Carbon Film Resistor	4	Brown-Black-Black	<input type="checkbox"/>
R14	100Ω 5W Metal Film Resistor	1	Brown- Black- Brown	<input type="checkbox"/>
C23	1000 pf Silver Dipped Mica Capacitor	1	1000 or 102 / 500V	<input type="checkbox"/>
C11, C12 C13, & C14	120 pf Silver Dipped Mica Capacitor	4	120 / 500V	<input type="checkbox"/>
C19, C20, C21, C22				
C25, C26, C27, C28	.01 uf Ceramic Disc Capacitor	8	103	<input type="checkbox"/>
C15, & C16	330pf Silver Dipped Mica Capacitor	2	330 /500V	<input type="checkbox"/>
C17, & C18	820pf Metal Clad Capacitor	2	820	<input type="checkbox"/>
C24	150 pf Metal Clad Capacitor	1	150	<input type="checkbox"/>
C29	22 uf Electrolytic Capacitor	1	22 uf / 25V	<input type="checkbox"/>
C30	10 pf Ceramic Disc Capacitor	1	10	<input type="checkbox"/>
VC1	Mica Compression Trim Capacitor	1	465	<input type="checkbox"/>
D1	3A / 1000V PIV Silicon Rectifier	1	1N5408	<input type="checkbox"/>
D2	1A / 1000V PIV Silicon Rectifier	1	1N4007	<input type="checkbox"/>
D3	Glass Signal Diode	1	1N4148	<input type="checkbox"/>
D4	LED Indicator assy.	1	Blue LED / Resistor Pkg.	<input type="checkbox"/>
TR2, TR3				
TR4, & TR5	200 Watt RF Power Transistor	4	2SC2879	<input type="checkbox"/>
TR6	NPN Switching Transistor / TO-92	1	PN2222A	<input type="checkbox"/>
CHK8, 9, 10				
11, 12, & 13	½" x ½" Ferrite Core	6		<input type="checkbox"/>
CHK2, 3, 6, & 7	¼" x ½" Ferrite Core	4		<input type="checkbox"/>
T3, & T4	½" x ½" Ferrite Transformer Core	2		<input type="checkbox"/>
T5, T6	½" x 2" Ferrite Transformer Core	2		<input type="checkbox"/>
SW1	SPST Switch	1		<input type="checkbox"/>
RLY1	DPDT Relay 12V Coil /10A Contacts	1		<input type="checkbox"/>
FAN1	4.7" Fan Assy.	1		<input type="checkbox"/>
FG1	4.7" Fan Guard	1		<input type="checkbox"/>
Conn1, Conn2	Panel Mount SO239 UHF Connector	2		<input type="checkbox"/>
Conn3	¼" Stereo Phone Jack	1		<input type="checkbox"/>
Cabinet	Aluminum Enclosure Assy.	1		<input type="checkbox"/>

Designator	Description	QTY	Code	Check
HS1	Aluminum Heat Sink	1		<input type="checkbox"/>
CB1	Pre-Drilled Copper Clad Circuit Board	1		<input type="checkbox"/>
CB2	Copper Clad Circuit Board 5-1/8" x 3/4"	1		<input type="checkbox"/>
PS1, & 2	4 Position Pre-Cut Transistor / Pill Strips	2		<input type="checkbox"/>
SCK1	LED Mounting Clip w/ LED Assy.	1		<input type="checkbox"/>
WIRE-1	10" Length of #20 Silver/Teflon Wire	1		<input type="checkbox"/>
WIRE-2	93" Length of #16 Silver/Teflon Wire	1		<input type="checkbox"/>
WIRE-3	3" Length of #14 Silver/Teflon Wire	1		<input type="checkbox"/>
WIRE-4	25" Length of #20 Hook-up Wire (Color 1)	1		<input type="checkbox"/>
WIRE-5	18" Length of #20 Hook-up Wire (Color 2)	1		<input type="checkbox"/>
WIRE-6	12" Length of #10 Red Power Cable	1		<input type="checkbox"/>
WIRE-7	12" Length of #10 Black Power Cable	1		<input type="checkbox"/>
COAX	7" Length RG316 Coax	1		<input type="checkbox"/>
HDW1	Hardware Kit (See Below)			
	SHCS #4 40 x 1/4" Socket screw	12		<input type="checkbox"/>
	SHCS #6 32 x 1/4" Socket screw	12		<input type="checkbox"/>
	Pan Head Sheet Metal Screw	6		<input type="checkbox"/>
	Pan Head Machine Screw #6 32 x 1/2"	8		<input type="checkbox"/>
	#6 Lock Washer	6		<input type="checkbox"/>
	#6 32 TPI Machine Nut	4		<input type="checkbox"/>
	#6 Solder Lug	3		<input type="checkbox"/>
	Pan Head Machine Screw #8 32 x 1-1/2"	4		<input type="checkbox"/>
	#8 32 TPI Machine Lock Nut (Nylock)	4		<input type="checkbox"/>
	Rubber Feet	4		<input type="checkbox"/>
	Rubber Grommet	1		<input type="checkbox"/>
	Scrap circuit board material	1		<input type="checkbox"/>
	Heat sink lubricant	1		<input type="checkbox"/>
	Label Sheet	1		<input type="checkbox"/>
	4" Cable Tie	4		<input type="checkbox"/>

**Tools Needed:** Standard electronic hand tools consisting of but not limited to:

- Diagonal wire cutters (4-1/2" flush-cut are the best)
- Needle nose pliers (4-1/2" with 1/8" dia. tips for shaping component leads, not those super long ones.)
- Good pair of tweezers (Serrated jaws are best)
- De-soldering tools if needed (Solder Wick, Manual solder sucker, Pace or equiv. powered de-solder station)

Everybody has their favorite hand tools that they use to perform a particular task, so the following pages will only list tools as a heads-up of some special items that are needed. The use of common sense is your best tool.

# Assembly Instructions

---

## Step 1

**Parts Needed:** Heat Sink (HS1)  
Circuit Board (CB1)  
1ea. 200 Watt RF Power Transistors  
4ea. SHCS #4-40 Socket Machine Screw

**Tools Needed:** Ultra Fine *Sharpie* Marker  
Power Drill (Battery powered is best)  
1/8" drill bit  
3/32" drill bit (#40 size works better)  
Center Punch  
4-40 Tap & Handle (Needed if 3/32" drill bit used)

### Procedure:

- 1, Enlarge the six holes in the main circuit board as shown in photo frame #1. Position circuit board on top of heat sink as shown in photo frame #2 with the front edge of the board flush with the front edge of the heat sink. Center the circuit board on heat sink as to have about 3/8" over-hang on each side. Mark heat sink through the four holes of board as indicated in the photo.
- 2, Remove board and enlarge the four holes used to mark the heat sink by using the 1/8" drill bit as indicated in photo frame #2.
- 3, Use the center punch to mark drill points on heat sink. Bore the four drill points to a depth of about 3/8 of an inch with the 3/32" / #40 drill bit. If a 3/32" drill bit is used, then the four holes should be threaded with the 4-40 tap. If a #40 bit is used, the #4-40 x 1/4" screws will self tap.
- 4, Return board to heat sink and mount with the four #4-40 socket machine screws. Carefully place the power transistor in the left rear cut-out and mark the heat sink at the two transistor mount drill points. Carefully remove the transistor and do the same with the three rear remaining cut-outs. (The #1, & #2 front cut-outs are not used for this amp configuration) Return the transistor to its container. Remove circuit board from heat sink and bore the 8 holes using the same techniques used in procedure 3 with one exception, after boring the ten holes, dress the surface of the heat sink so that the bored holes are clean and flush. It is of the utmost importance that when the transistors are mounted, they make complete and full contact with the heat sink. A good counter sink bit turned by hand can assist in this task. When finished, slide a straight edge across heat sink to check for inconsistencies.
- 5, Remount the circuit board on heat sink. At this point, the assembly should look as that in photo frame #3

## Step 2

**Parts Needed:** Circuit board / heat sink assy.

- 6 ea. Pan Head sheet metal screws
- 1 ea. DPDT Relay (RLY1)
- 1 ea. 5-1/8" x 3/4" copper clad circuit board (CB2)
- Pre-cut transistor / pill strips (PS1, 2, 3, & 4)
- Bottom half of aluminum enclosure (Cabinet)
- 2ea. Panel Mount SO239 UHF connector (Conn1 & Conn2)
- 4ea. Pan Head machine screw #6-32 x 1/2"
- 2ea. #6 lock washer
- 4ea. 32 TPI machine nut
- 2ea. #6 solder lug

**Tools Needed:** Ultra Fine *Sharpie* Marker

- 5 Minute Epoxy
- #2 Phillips screw driver
- Pliers or wrench for #6 machine nuts

**Procedure:**

1, Mount both SO239 UHF connectors from the inside of the enclosure making sure that the cut-out on the center conductor of the connector is facing up. Use the lock washers on the upper mounting holes and the solder lugs on the lower. **Tip:** Set the nuts on the lower screws so that one of the flats of the nut is facing down as to allow the bending of the solder lug. This will provide clearance that may be needed later. See photo frame #4 for reference.

2, Bend solder lugs up as shown in photo frame #4. Lower circuit board / heat sink assy. into the enclosure and slide under the two bent up solder lugs all the way back until it is against the back of the enclosure. At this point the six mounting holes on the right and left sides of the circuit board should line up with the six pre-drilled holes in the enclosure. Mount the circuit board to enclosure using at least four of the six pan head sheet metal screws. See photo frame #5 for reference.

3, Position DPDT relay with the terminals forward, and in such a way that the two terminals of the relay coil are on the bottom and the relay itself is centered between the two UHF connectors and against the rear panel of the enclosure. Mark the two front corners of the relay on the main circuit board as shown in photo frame #6. Now position the 5-1/8" x 3/4" copper clad circuit board (foil side up) just in front of the rear main circuit board mounting screws; and centered on the main circuit board. Mark the two front corners of the 5-1/8" x 3/4" copper clad circuit board on the main circuit board as shown in photo frame #6. Remove the 5-1/8" x 3/4" board and relay, and set aside. Remove the mounting screws, and the main circuit board / heat sink assy. from the enclosure.

4, Reposition on the main circuit board / heat sink assy. the 5-1/8" x 3/4" circuit board and relay. (Remember, the two coil terminals of the relay are at the bottom) Now position the two transistor / pill strips (foil side up) as shown in photo frame #7.

**It is important to read the following in its entirety, as the next process must be performed in one fluid action.**

Once you get a good feel where everything needs to be located, mix some 5 minute epoxy where the final amount of the two mixed components is about the diameter of a quarter dollar and 3/16" high. The previous statement for the quantity is just for reference, but should be enough to perform the next process. Once the epoxy is good and mixed, remove the previously positioned components one at a time starting with the first pill strip. Apply a light coating of epoxy to the bottom, reposition right back where it came from. Do the same with the rest of the pill strips. Now mount the 5-1/8" x 3/4" circuit board at its assigned location. Take the rest of the mixed epoxy and apply to the relay and place at its marked position. Now go back and reposition any of the components that may have shifted.

As the epoxy sets, remove any extra that may have oozed over the edge at the rear of the relay.

Take a break and have a cup of coffee.

## Step 3

**Parts Needed:** Circuit board / heat sink assy.

- 4 ea. 2SC2879 RF Power Transistors (TR2, TR3, TR4, & TR5)
- 2 ea. 1/2" x 1/2" Ferrite Transformer Cores (T3, & T4)
- 2 ea. 1/2" x 2" Ferrite Transformer Cores (T5, & T6)
- 8ea. #4-40 x 1/4" Socket machine screws

**Tools Needed:** 3/32" T-handle Allen wrench (Regular Allen wrench may be used)

- Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)
- 60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")
- Scrap circuit board material (Included in hardware kit)
- Heat sink lubricant (Included in hardware kit)
- X-acto knife or Olfa knife
- Small 1/8" blade straight slot screw driver (Jewelers type is best)

### **Procedure:**

1, Make sure that all four transistor mounting wells are clear of epoxy ooze (Trim with X-acto knife if needed) and clean heat sink in the transistor wells with a Q-tip to remove any debris. Trim the corner of the plastic bag containing the heat sink lubricant. Squeeze equal amounts of lubricant into the center of each transistor wells until all of the lubricant is used. Seat the four transistors marked 2SC2879 (TR2, TR3, TR4, & TR5) in the four rear wells with their collector legs pointing to the rear. Notice that the collector leg of the transistor has a bevel cut in it, and should be pointing to the rear. Firmly push straight down on top of the transistors until they are fully and completely seated. Be very careful not to bend the mounting tabs of the transistor as they are made of soft metal. When finished, the assy. should look just like photo frame #8.

2, This is another point at which we need to be very careful, as we don't want to twist off the head of any of the #4-40 socket machine screws. With all the transistors fully seated, thread the machine screws through the mounting tabs of each of the transistors and into the heat sink. Just make them good and snug, not super tight. Believe me; you don't want to have to deal with drilling out a steel #4 screw mounted in aluminum. This is supposed to be fun! If you used a #40 drill bit when boring the transistor mounting holes, the #4-40 screws will self thread. However if there is undo resistance, back off a couple turns and then continue the self threading process. Once all the transistors are mounted, bend the legs as instructed in photo frame #9.

3, Gentlemen, heat up your soldering irons! We will presume you have good soldering skills, so we will not get into a soldering lesson. However, if there are any questions, please give us a call or Email. Solder the emitter legs of each transistor to the main circuit board assy. as shown in photo frame #10.

4, Take one of the 1/2" long ferrite transformer cores (T4) and look at each end, you will notice that on one of the ends, the two brass tubes that comprise the primary winding is not connected. The non connected side from now on will be referred to as the "front" of this and all transformers. On the front of the transformer you will also notice that the two solder pads **may** narrow on one side, this will be considered the bottom edge and also the side that will be soldered to the pill strips. See photo frame #11. (On transformers that do not narrow, either edge can be soldered to the pill strips.)

6, Rotate the assy. to the 180° on the work surface. Take one of the two 1/2" long ferrite transformer cores which will become (T4) and set the front end of the transformer with the bottom edge down on the part of the pill strip that coincides with the base legs of transistors (TR4, & TR5). Place the scrap piece of circuit board material under the rear of the transformer to keep it level. Adjust the transformer so that the separation cut in the pill strip is in the center between the two solder pads of the transformer and the bottom front edge just touches the base legs of transistors (TR4, & TR5). Carefully solder each of the transformer solder pads to the pill strip pads on which they sit by starting on one side and then moving to the next, while doing so let the base legs of the power transistors become soldered to the pill strip pad as well. Use enough solder as to create a good fillet that will help support the transformer. See photo frame #12. Remove the scrap circuit board material and set aside.

7, Take the remaining 1/2" long ferrite transformer core which will become (T3) and set the front end of the transformer with the bottom edge down on the part of the pill strip that coincides with the base legs of transistors (TR2, & TR3). Place the scrap piece of circuit board material under the rear of the transformer to keep it level. Adjust the transformer so that the separation cut in the pill strip is in the center between the two solder pads of the transformer and the bottom front edge just touches the base legs of transistors (TR2, & TR3). Carefully solder each of the transformer solder pads to the pill strip pads on which they sit by starting on one side and then moving to the next, while doing so let the base legs of the power transistors become soldered to the pill strip pad as well. Use enough solder as to create a good fillet that will help support the transformer. See photo frame #12. Remove the scrap circuit board material and set aside.

**I know we keep repeating ourselves, but it's just so we don't make any mistakes.**

8, Rotate the assy. 180° on the work surface. Take one of the two 2" long ferrite transformer cores which will become (T5) and set the front end of the transformer with the bottom edge down on the part of the pill strip that coincides with the collector legs of transistors (TR2, & TR3). Place the scrap piece of circuit board material under the rear of the transformer to keep it level. Adjust the transformer so that the separation cut in the pill strip is in the center between the two solder pads of the transformer and the bottom front edge just touches the collector legs of transistors (TR2, & TR3). Carefully solder each of the transformer solder pads to the pill strip pads on which they sit by starting on one side and then moving to the next, while doing so let the collector legs of the power transistors become soldered to the pill strip pad as well. Use enough solder as to create a good fillet that will help support the transformer. See photo frame #13. Remove the scrap circuit board material and set aside.

9, Take the remaining 2" long ferrite transformer core which will become (T6) and set the front end of the transformer with the bottom edge down on the part of the pill strip that coincides with the collector legs of transistors (TR4, & TR5). Place the scrap piece of circuit board material under the rear of the transformer to keep it level. Adjust the transformer so that the separation cut in the pill strip is in the center between the two solder pads of the transformer and the bottom front edge just touches the collector legs of transistors (TR4, & TR5). Carefully solder each of the transformer solder pads to the pill strip pads on which they sit by starting on one side and then moving to the next, while doing so let the collector legs of the power transistors become soldered to the pill strip pad as well. Use enough solder as to create a good fillet that will help support the transformer. See photo frame #13. Remove the scrap circuit board material and discard as it is no longer needed.

10, When finished, the assy. should look as that in photo frame #14.

## Step 4

**Parts Needed:** Circuit board / heat sink assy.

- 4 ea. 10 $\Omega$  1/2W carbon film resistor (R6, R7, R8, & R9)
- 4 ea. 120pf @ 500V Silver Dipped Mica Capacitor (C11, C12, C13, & C14)
- 1 ea. 1A / 1000V PIV Silicon Rectifier (D2) (Small)

**Tools Needed:** Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)  
60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

**Procedure:**

- 1, Take the four 10 $\Omega$  1/2W resistors, bend and trim as shown in photo frame #15.  
Solder these resistors in place as shown in photo frame #16.
- 2, Take the four 120pf capacitors, bend and trim as shown in photo frame #18. (Note: There is no photo frame #17)  
Solder these capacitors in place as shown in photo frame #19.
- 3, Take the 1A rectifier and attach to the two lower relay coil terminals as shown in photo frame #20, pay attention to polarity and **DO NOT** solder yet.
- 4, Carefully bend-up the two top relay terminals as shown in photo frame #21

## Step 5

**Parts Needed:** Circuit board / heat sink assy.

- 1 ea. 25-1/2" length of #16 Silver/Teflon wire (WIRE-2)
- 1 ea. 1000pf / 500V Silver Dipped Mica Capacitor (C23)
- 1 ea. 150pf Metal Clad Capacitor (C24)
- 1 ea. 45" length of #16 Silver/Teflon wire (WIRE-2)
- 2 ea. 1/2" x 1/2" Ferrite Core (CHK12, & CHK13)
- 1 ea. 100 $\Omega$  5 Watt Metal Film Resistor (R14)
- 1 ea. 1" Length of #16 Silver/Teflon wire (WIRE-2)

**Tools Needed:** Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)  
60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

**Procedure:**

- 1, Take the 25-1/2" length of #16 Silver/Teflon wire, straighten and fold exactly in half. Mark the center, and trim away 1/4" of insulation from both sides of the center line, for a total of 1/2" insulation removed. Bend the wire to form the shape shown in photo frame #22. Take one of the 1/2" x 1/2" ferrite cores (CHK12), which will become the power splitter (SLT1) and place over one of the legs of the wire, slide the core up the wire to within 3/8" of the little loop you just created. Bring the other leg of the wire around and insert it in the other side of the core, pull tight and re-adjust until this assy. is like that shown in photo frame #23. Take one of the wires and bring the end around and insert it in the opposite side of the core, pull through to make a tight winding on the core, do this one more time for a total of two tight windings. Take the other wire and do the same as the first, although in the opposite direction. To assist in this task, see photo frames #24, #25, & #26.

2, Take one of the wires of the power splitter you just made and run it through the inner most tube of (T3), now take the other wire of the splitter and run it through the inner most tube of (T4) as shown in photo frame #27. Position the splitter itself centered right up between the two transformers. Take the wire that is exiting the rear of (T3) and pull it forward through the left tube as shown in photo frame #28. Now feed the wire back through the right tube under the first winding as shown in photo frame #29. (As each of these turns is made, keep them as tight as possible) Feed the wire back through the left tube again under the previous winding as shown in photo frame #30. Do this one more time; so that there is a total of three windings on (T3), making sure that each new winding is under the previous. When done, your windings should look like those in photo frame #31. Now do the same to (T4) with the other wire. Remember to keep each new winding under the previous, and to have three turns of wire just like (T3). When you are finished, your work should look like photo frame #32. Trim both wires so that there is 3/4 of an inch protruding from each of the transformers. Remove 1/4" of insulation from the end of each wire, and solder to the main circuit board as shown in photo frame #33.

3, Now we are going to build the same type of assy. as the power splitter, albeit with a slight modification. But first, we need to prepare the relay. Take the 1000pf / 500V silver dipped mica capacitor (C23), bend and trim as shown in photo frame #34. Take this capacitor (C23) and the 150pf metal clad capacitor (C24) and assemble as shown in photo frame #35. Solder and trim as shown in photo frame #36. Solder this capacitor assy. to the main circuit board as shown in photo frame #37.

4, OK, here we go. Take the 45" length of #16 Silver/Teflon wire, straighten and fold exactly in half. Mark the center, and trim away 1/4" of insulation from both sides of the center line, for a total of 1/2" insulation removed. Bend the wire to form the shape shown in photo frame #38. Take one of the 1/2" x 1/2" ferrite cores (CHK13), which will become the power combiner (CMB1) and place over one of the legs of the wire, slide the core up the wire to within 3/8" of the little loop you just created. Bring the other leg of the wire around and insert it in the other side of the core, pull tight and re-adjust until this assy. is like that shown in photo frame #39. Take one of the wires and bring the end around and insert it in the opposite side of the core, pull through to make a tight winding on the core, do this one more time for a total of two tight windings. Take the other wire and do the same as the first, although in the opposite direction. To assist in this task, see photo frames #40, #41, & #42.

5, Remove the insulation from the combiner (CMB1) in the two locations as shown in photo frame #43. Take the 100Ω 5W resistor (R14) and wrap the leads around each of the two wires of (CMB1) where the insulation was removed, as shown in photo frame #44. Solder and trim as shown in photo frame #45. Take the combiner assy. and insert one of the wires into the inner most tube of transformer (T5), and take the other wire and insert it into the inner most tube of transformer (T6). Pull these two wires through the transformers until the loop of the combiner (CMB1) can rest on the relay terminal as shown in photo frame #46. Take the unattached lead of (C23) and insert it into and through the loop of the combiner (CMB1) and the hole of the relay terminal, bend the capacitor lead straight up and trim as shown in photo frame #47. Squeeze this connection with non-serrated pliers and solder as shown in photo frame #48.

6, With the circuit board / heat sink assy. oriented so that the relay is positioned away from you, feed the wire that protrudes from the right tube of (T5) into the left tube and pull tight as shown in photo frame #49. Now take the wire and feed it back through the right tube, pulling toward you while keeping it under the first winding. After pulling the wire tight, it should look like that in photo frame #50. Keep threading in and out of the transformer until there are three windings on (T5), remember that each new winding should be under the previous. Refer to photo frames #51, #52, & #53. Once the windings are nice and tight, trim the end of the wire so that only 1" remains as shown in photo frame #54. Trim 1/4" of insulation from the end of the wire, and bend around the transformer as shown in photo frame #55. Solder wire to the main circuit board as shown in photo frame #56. Now perform the same procedure on (T6), but of course winding in the opposite direction. When you are finished, it should look like photo frame #57.



7, Take the 1" length of #16 Silver/Teflon wire and remove 3/4" of insulation. The 1/4" of insulation remaining will hold the strands of wire together. Place this wire across the two top bent terminals of the relay as shown in photo frame #58. Solder and trim as shown in photo frame #59.

## Step 6

**Parts Needed:** Circuit board / heat sink assy.

- 1 ea. #465 Mica Compression Trimmer Capacitor (VC1)
- 1 ea. 3-3/4" Length of #16 Silver/Teflon wire (WIRE-2)
- 2 ea. 4.7Ω 2W Carbon Film Resistor R4, & R5
- 2 ea. 4-3/4" length of #20 Silver/Teflon wire (WIRE-1)
- 2 ea. 1/4" x 1/2" Ferrite Core (CHK6, & CHK7)
- 4 ea. 100Ω 2W Metal Film Resistor (R10, R11, R12, & R13)
- 4 ea. 0.01uf Ceramic Disc Capacitor (C19, C20, C21, & C22)
- 2 ea. 820pf Metal Clad Capacitors (C17 & C18)
- 2 ea. 330pf / 500V Silver Dipped Mica Capacitor (C15, & C16)

**Tools Needed:** Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)  
60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

### Procedure:

1, Take the trimmer capacitor (VC1) and prepare as shown in photo frame #60. Solder to the main circuit board as shown in photo frame #61.

2, Take the 3-3/4" length of #16 wire and remove 1/4" of insulation from each end. Insert one end of the wire into the loop of (SLT1) as shown in photo frame #62. Solder and trim as shown in photo frame #63. Insert the other end and wrap around the top terminal of (VC1) as shown in photo frame #64.

3, Prepare the two 4.7Ω resistors as shown in photo frame #65. Feed one lead of the resistor assy. through the hole in the top terminal of (VC1), wrap around and trim as shown in photo frame #66, (Notice the orientation of the resistors). Solder as shown in photo frame #67.

4, Take the two 4-3/4" lengths of Silver/Teflon wire and prepare the three ferrite cores (CHK6, & CHK7) as shown in photo frame #68. Take the prepared ferrite core CHK6, and solder the longer lead to transformer (T3), and the shorter 3/4" long lead to the main circuit board as shown in photo frame #69. Take the prepared ferrite core CHK7, and solder the longer lead to transformer (T4), and the shorter 3/4" long lead to the main circuit board, again as shown in photo frame #69.

5, Prepare four (4) harmonic suppression feed-back circuits by using the 100Ω resistors, the 0.01uf capacitors and the instructions in photo frame #70. **Note:** Save two lead clipping from two of the resistors for later. The next process can be a little tricky to hold with your fingers, so we recommend using a good pair of tweezers. Solder the capacitor end of the feed-back circuit to the forward pill strip, and then bend the leads as necessary to reach over to the other pill strip. It's a good idea to line things up before doing any soldering. Please see photo frames #71, & 72 for component placement.

6, Solder the body of each of the two (2) metal clad capacitors (C17, & C18) to the right solder pad, flush with the top edge of transformers (T5, & T6) as shown in photo frame #73.

7, Take the two scrap wire clippings from procedure #5, and bend as shown in photo frame #74.

8, Take one of the bent scrap wire clippings and “Hook” the terminal hole of (C17), and squeeze with non-serrated pliers as shown in photo frames #75 & #76. Do the same to (C18) with the other bent wire clipping.

9, Solder both capacitor wire attachments as shown in photo frame #77. Bend each wire and trim as shown in photo frame #78. Solder each wire to the left solder pad of it’s transformer as shown in photo frame #79. When finished, they should look like photo frame #80.

10, Take both of the 330pf silver dipped mica capacitors (C15, & C16) and trim their leads down to 1/4". Solder one each to transformers (T3, & T4) as shown in photo frame #81.

## Step 7

**Parts Needed:** Circuit board / heat sink assy.

Switching Transistor (TR6)

Glass Signal Diode (D3)

22uf Electrolytic Capacitor (C29)

10pf Ceramic Disc Capacitor (C30)

2 ea. 1/2" x 1/2" Ferrite Core (CHK8, & CHK9)

2 ea. 6-1/2" Length of #16 Silver/Teflon wire (WIRE-2)

1 ea. 3" Length of #14 Silver/Teflon wire (WIRE-3)

**Tools Needed:** Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)

60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

### Procedure:

1, Take the switching transistor and bend legs as shown in photo frame #82. Attach the 22uf electrolytic capacitor to the switching transistor as shown in photo frame #83, observe polarity. Attach the glass signal diode to the transistor/capacitor assy. as shown in photo frame #84, observe polarity. Attach the 10pf ceramic disc capacitor as shown in photo frame #85. Solder and trim as shown in photo frame #86, **Do Not** solder the full length of the twisted leads as they will need to be bent in the following procedures.

2, Take the two legs of the T/R relay drive circuit where (TR6's) collector and (C29's) positive lead are twisted together, and insert through the hole in the relays coil terminal where (D2's) anode is connected. Insert until the body of the transistor touches the relay, wrap these leads around terminal and trim as shown in photo frame #87. Solder as shown in photo frame #88. Take the free lead of the disc capacitor and thread through the hole in the relay terminal, bend over, and trim as shown in photo frame #89, but **Do Not** solder. Trim the remaining twisted leads and solder these leads to the main circuit board as shown in photo frame #90.

3, Take the two (2) ferrite cores, the two (2) 6-1/2" lengths of silver/Teflon wire, and prepare as shown in photo frame #91. Solder the 3/4" leads of each prepared choke (CHK8, & CHK9) to the rear of each transformer (T5, & T6) as shown in photo frame #92. Carefully bend down the power chokes and solder their leads to the 5-1/8" x 3/4" copper clad circuit board (CB2) as shown in photo frame #93.

4, Take the 3" length of #14 silver/Teflon wire, and completely remove the insulation. Place the wire on the 5-1/8" x 3/4" copper clad circuit board (CB2) so that it overlaps the leads of the two power chokes just soldered. Over-solder this wire at the same two points the chokes were soldered exactly as shown in photo frame #94. (This wire is for current flow reinforcement).

## Step 8

**Parts Needed:** Circuit board / heat sink assy.

- 1 ea. 3A / 1000V Rectifier (D1)
- 4 ea. .01uf Ceramic Disc Capacitor (C25, C26, C27, & C28)
- 1 ea. Aluminum Enclosure assy. (Bottom half)
- 6 ea. Pan Head Sheet Metal Screws
- 2 ea. 2-1/4" Length of #16 Silver/Teflon wire (WIRE-2)
- 1 ea. 1/4" Phone Jack (Conn3)
- 1 ea. SPST Switch (SW1)
- 1 ea. LED Mounting Clip (SCK1)
- 1 ea. LED Assy. (D4)
- 1 ea. Rubber Grommet
- 1 ea. 12" Length Red #10 Power Cable (WIRE-6)
- 1 ea. 12" Length Black #10 Power Cable (WIRE-7)
- 2 ea. 1/2" x 1/2" Ferrite Core (CHK10, & CHK11)
- 2 ea. 4" Cable Tie

**Tools Needed:** Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)  
60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

### Procedure:

- 1, Take the 3A rectifier, bend and solder as shown in photo frames #95, & 96.
- 2, Take the four (4) .01uf ceramic disc capacitors, bend and trim as shown in photo frame #97. Solder two (2) of these capacitors at each end of the 5-1/8" x 3/4" circuit board as shown in photo frame #98, #99, & #100.
- 3, It's starting to come together! Take the Circuit board / heat sink assy. and mount in the bottom half of the enclosure using all six (6) sheet metal screws as shown in photo frame #101. Bend down both solder lugs as shown in photo frame #102. Solder both lugs to the main circuit board as shown in photo frame #103.
- 4, Take one of the 2-1/4" long #16 Silver/Teflon wires, remove 1/4" of insulation from both ends and solder to the output UHF connector as shown in photo frame #104. Take the free end of this wire and insert it into the relay terminal as shown in photo frame #105. Squeeze this connection with non-serrated pliers to flatten, and solder as shown in photo frame #106. Take the other 2-1/4" long #16 Silver/Teflon wire, remove 1/4" of insulation from both ends and solder to the input UHF connector as shown in photo frame #107. Take the free end of this wire and insert it into the relay terminal next to the lead from (C30) as shown in photo frame #108. Squeeze this connection with non-serrated pliers to flatten, and solder as shown in photo frame #109.
- 5, Install phone jack as shown in photo frame #110, it's a good idea to leave finger tight, as we might want to rotate later. Prepare switch as shown in photo frame #111. Install switch as shown in photo frame #112. Install LED mounting clip as shown in photo frame #113. Prepare LED assy. as shown in photo frame #114. Install LED assy. as shown in photo frame #115.
- 6, Solder the black lead of the LED assy. to the main circuit board as shown in photo frame #115. Attach red wire of the LED assy. as shown in photo frame #116. Install the rubber grommet as shown in photo frame #117. Remove 1/2" of insulation from one end of each of the #10 power cables, insert the black cable through the grommet and solder to the main circuit board, insert the red cable through the grommet, install the two (2) ferrite cores, and solder to the 5-1/8" x 3/4" circuit board over the current reinforcement wire as shown in photo frame #118.

## Step 9

**Parts Needed:** Amplifier Chassis & Enclosure cover assy.

- 1 ea. 11" Length #20 Hook-up Wire (WIRE-4)
- 1 ea. 1/4" x 1/2" Ferrite Core (CHK2)
- 1 ea. 13-1/4" Length #20 Hook-up Wire (WIRE-4)
- 1 ea. 12" Length #20 Hook-up Wire (WIRE-5)
- 1 ea. 5" Length #20 Hook-up Wire (WIRE-5)
- 1 ea. 9" Length of RG-316 Coax Cable (COAX)

**Tools Needed:** Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)  
60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

### Procedure:

1, Prepare the 11" length of hook-up wire and the 1/4" x 1/2" ferrite core as shown in photo frame 119. Attach but do not solder the 5" lead to the bottom terminal of the switch (SW1), solder the 3-1/4" lead to the 5-1/8" x 3/4" circuit board as shown in photo frame #120. Take the 13-1/4" length of hook-up wire and remove 1/4" of insulation from each end, connect one end to the bottom terminal of the switch (SW1) along with the previously attached wire and solder as shown in photo frame #121. **(Read note below before soldering!)**

**NOTE: When soldering wires to the switch, make sure that it is in the "Off" (Lever down) position. Also solder wires as quickly as possible, as excess heat on solder terminals can damage the switch.** Route this 13-1/4" length of #20 wire as shown in photo frame #121. Before attaching the end of this wire, please study photo frame #122. Once the terminals of the phone jack are identified, attach wire as shown in photo frame #123.

2, Attach and solder one end of the 12" wire as shown in photo frame #124. Route and attach this wire to the phone jack terminal that will connect to the "RING" of the phone plug when it is inserted, as shown in photo frames #125, & #126. Use the two (2) cable ties as shown. Take the 5" length of hook-up wire and remove 1/4" of insulation from each end, attach and solder one end of this wire to the relay coil terminal that already has the cathode of (D2) attached, as also shown in photo frame #127. Attach the other end of this wire to the phone jack terminal that will connect to the "RING" of the phone plug when it is inserted, as shown in photo frame #127.

3, Prepare the 9" length of RG-316 coax as shown in photo frames #128, & #129. Attach and solder the end of the coax that is 4" from the shield grounding point to the top terminal of VC1 as shown in photo frames #130 & 131. Attach and solder the other end of coax as shown in photo frame #132, & 133. Shape, and route the coax cable, then solder the shield grounding point the main circuit board as shown in photo frame #134.

4, Take the enclosure cover, mark and bore a access hole for VC1 as shown in photo frames #135, 136, & 137.

5, Oh, I'm sorry. I forgot to say take a break for coffee. By all means more COFFEE!

## Step 10

**Parts Needed:** Enclosure cover assy.

- 1 ea. 4.7" 12V Fan Assy. (FAN1)
- 1 ea. 4.7" Fan Guard (FG1)
- 1 ea. 11" Length #20 Hook-up Wire (WIRE-4)
- 1 ea. 1/4" x 1/2" Ferrite Core (CHK3)
- 1 ea. 4.7Ω 2W Carbon Film Resistor (R15)
- 1 ea. #6 Solder Lug
- 4 ea. #8-32 x 3/4" Pan Head Machine Screw
- 4 ea. #8-32 Machine Lock Nut

**Tools Needed:** Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)  
60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

**Procedure:**

1, Prepare the 4.7Ω resistor as shown in photo frame #138. Prepare the cooling fan as shown in photo frame #139.

**Note: Holes may have already been bored.** Mount the resistor as shown in photo frames #140, #141, & #142. Cut and trim the red / B+ wire of the fan, and solder to the loop in the resistor lead as shown in photo frame #143. Take the of the red wire you just cut off and remove 1/4" of insulation from one of the ends, solder the stripped end to the other leg of the resistor as shown in photo frame #144. Wrap the wire around the ferrite core (CHK3) three (3) times and route wire as shown in photo frame #145. Cut and strip the black / B- wire of the fan, and solder to the solder lug as shown in photo frame #146. Modify this solder lug as shown in photo frame #147 so that it may be threaded on a #8 pan head machine screw.

2, Mount the fan assy. to the enclosure cover exactly as shown in photo frame #148 using the #8 machine screws, lock washer, and nuts. **Note: Don't forget the hole drilled for VC1.** Photo frame #149 shows top view of cover after the fan assy. has been installed.

3, Set the assembled cover to the side, it's time to test and calibrate your new amplifier.

## Step 11

**Parts Needed:** Amplifier Assy. (Cover not attached)

**Tools Needed:** -12~20VDC power supply capable of supplying a constant current of 100 amps or better.  
-10/11 meter transceiver with a peak envelope power no greater than 100 watts.  
-Bird 43 watt meter with “peak reading upgrade” and 1000W/ 25~60 MHz. element or equivalent.  
-Coax jumper with PL259 connectors at each end.  
-1000W dummy load or antenna system with a good standing wave ratio (SWR).

**The following are very useful but not necessary**

-Sweep audio generator with an adaptor that mates with microphone plug on transceiver and has a switch that keys transmitter. (We use a Wavetek model 188)  
-100 MHz. oscilloscope (We use a Hitachi model V-1065)  
-600 MHz. RF spectrum analyzer (We use a Hameg model HM5006)  
-Other RF taps and connectors as needed.

### **Procedure: Basic Calibration & Test**

- 1, Connect amplifier as shown in photo frame #150.
- 2, Power up transceiver and select a mid-band frequency.
- 3, Keep amplifier “OFF”.
- 4, With the transceiver keyed, and while saying the word “Audio” into the microphone, observe power meter for forward deflection.
- 5, Turn amplifier “On”.
- 6, Key-up transceiver with no audio and observe power meter for forward deflection.
- 7, With the transceiver keyed, and while saying the word “Audio” into the microphone repeatedly at 1 second intervals, adjust VC1 for maximum forward deflection.  
Never operate where the needle swings backwards, as this is an indication of transistor saturation.
- 8, Turn “On” the peak reading function of the meter. Key-up transceiver with audio and observe peak output.
- 9, See photo frame #151 for performance data.

## Step 12

**Parts Needed:** Enclosure Bottom / Amplifier Assy.

Enclosure Cover / Fan Assy.

12 ea. #6 32 x 1/4" Socket screw

4 #6 Pan Head Machine Screw #6 32 x 1/2"

4 #6 Lock Washers

4 Rubber Feet

Self Adhesive Label Sheet

**Tools Needed:** -7/64" T-handle Allen wrench (Regular Allen wrench may be used)

-Soldering Iron (A good 40~50 watt iron with a 1/16" chisel tip is best)

60/40 resin core solder or equiv. (We use Kester 63/37 @ .031")

**Procedure:**

1, Take the enclosure cover/fan assy. and position as shown in photo frame #152. Cut back the fan power wire to the length necessary to allow the wire to be soldered to the lug of the 1/4" phone jack that carries switched supply power. Remove 1/4" of insulation and solder to the appropriate lug as shown in photo frame #152.

2, Position cover/fan assy. on lower chassis and install twelve (12) #6 32 x 1/4" socket screws as shown in photo frame #153.

3, Install the four (4) rubber feet using the #6 machine screws and lock washers as shown in photo frame #154.

4, Take label sheet, cut apart, peel, and place on rear panel as shown in photo frame #155.

**Congratulations, you are now the proud owner of a high quality high performance HF linear amplifier that you built yourself!**