

This Information Is Provided By  
***CBTricks.com***

Craig L102 Service Bulletin# 041178

**Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!**

**Modifications are provided for information purposes only!**

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

**Thank you for any support you can give.**

For information on how to Support CBTricks.com

<http://www.cbtricks.com/support/>

**SOUND  
ADVICE**

**CRAIG**

SB# 041178  
April 11, 1978

To: All Warranty Service Centers

From: Mike Taylor, Technical Service Manager

Subject: L102 CB Transceiver

Problem: Wrong or incomplete digits displayed on Channel indicator.

Solution: Cover screw nearest the front of the unit, on the right side, may be too long and contacting the channel selector switch.

The screw used in this location should not exceed  $\frac{1}{4}$  inch in length. Normally, there is no permanent damage to any of the components and replacing the screw with one of the proper length will restore operation of the display.

