



# SERVICE BULLETIN

PUBLISHED BY E. F. JOHNSON COMPANY / WASECA, MINNESOTA 56093

Consumer Radio  
#CB-72  
Mar. 29, 1973

## EQUIPMENT AFFECTED

Messenger 109  
Part #242-0109-XXX

## REASON FOR REVISION

Extremely severe operating conditions cause frequent breakage of standard antenna types.

## REVISION

Substitute flexible antenna

## PARTS REQUIRED

<u>QTY</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>
1	023-3207-001	Flexible antenna kit

## CHANGE ACTION

This revision should be used only in circumstances where the user is willing to accept considerable reduction in range, in exchange for a more rugged and compact antenna.

## IMPORTANT

DO NOT REVISE UNITS ACCORDING TO THIS BULLETIN UNLESS THE USER IS FULLY AWARE OPERATING RANGE WILL BE REDUCED AND AGREES TO ACCEPT THIS COMPROMISE IN ORDER TO PERMIT CONTINUED ROUGH USAGE AND HANDLING OF THE RADIOS.