



- Q101, Q107, Q301 : MPS9426 (C), 2SC1923
- Q102, Q103 : 2SK19
- Q104, Q106 : JF10335
- Q105 : MPS9623 (I)
- Q110, Q204, Q207 : MPS9631
- Q201, Q202, Q203 : MPS9634
- Q205 : MPS9618
- Q108, Q206 : MPS9681
- Q302 : 2SC1957, 2SC2314, 2SC1678
- Q303 : 2SC1306, 2SC495, 2SC2078
- Q401 : 2SD525 OR 2SD1082 (R)
- Q402 : 2SA950 (Y)
- Q403, Q404 : 2SC1815 (Y)



NOTES: A SERVICE PERSONNEL TO USE ONLY REPLACEMENT PARTS THAT HAVE THE CRITICAL CHARACTERISTICS RECOMMENDED BY THE MANUFACTURER.

B SERVICE PERSONNEL MUST MAKE LEAKAGE-CURRENT OR RESISTANCE MEASUREMENTS TO DETERMINE THAT EXPOSED PARTS ARE ACCEPTABLY INSULATED FROM THE SUPPLY CIRCUIT BEFORE RETURNING THE APPLIANCE TO THE CUSTOMER.

C SAFETY PRECAUTIONS TO BE OBSERVED DURING SERVICING WHEN TESTING WITH EXPOSED ELECTRICAL PARTS.

SCHEMATIC DIAGRAM