



EQUIPMENT AFFECTED

Messenger III, Part No. 242-0143-xxx  
Messenger III, Part No. 242-0150-xxx  
Messenger 100, Part No. 242-0152-xxx  
Messenger 100, Part No. 242-0156-xxx  
Messenger 102, Part No. 242-0102-xxx  
Messenger 110, Part No. 242-0110-xxx  
Messenger 123, Part No. 242-0123-xxx  
Messenger 124, Part No. 242-0124-xxx  
Messenger 124M, Part No. 242-0134-xxx  
Messenger 300, Part No. 242-0149-xxx  
Messenger 303, Part No. 242-0151-001/-007  
Messenger 320, Part No. 242-0320-xxx  
Messenger 323, Part No. 242-0153-xxx  
Messenger 323M, Part No. 242-0158-xxx  
Messenger 333, Part No. 242-0151-401/-407

REASON FOR REVISION

Transistor Substitution

REVISION

The 576-0003-009 (type 3009) transistors can be substituted for the 576-0003-010 (type 3010), IF and AGC transistors. Refer to Figure 1 for the different lead configuration.




Figure 1

CHANGE ACTION

Make this transistor substitution when the 3010 type is unavailable.