

ON OPERATION
lamps do not
indicate.

If fuse blown
CHECK:-D.C. cable
connector, L209
C132, C133 and switch

A

CHECK
power supply

standard
voltage
13.8 volts

fuse OK

CHECK
fuse

if blown
change fuse.

power
supplied
OK?

fuse blown

fuse OK

switch
on

Circuit is shorting
CHECK
switch
printed circuit board
wires
semiconductors
diodes

A

CHECK
connector

+: -RED
-: -BLACK

CHECK
L209, coil

L209 is between
connector and switch
check voltage
L209 to ground

CHECK
ON-OFF
switch

ON-OFF switch
and wiring

CHECK
.printed circuit board
.green RX lamp
.white pilot lamp
.D218
.PA, CB switch